



**Computer-Assisted 0.2kW Electromechanical
Training System (59-8006)**

Product Fix: LVDAM-EMS .dai files update for Mind-Sight server version 1.1.10 and higher

Affected Model(s): 9062-1x, Data Acquisition Interface

How to Fix: Extract all .dai files to the default samples directory :

64bits	→	C:\Program Files (x86)\Lab-Volt\LVDAM-EMS\Samples
32bits	→	C:\Program Files\Lab-Volt\LVDAM-EMS\Samples

Note: Overwrite existing files