

Release Date: 07/02/07

Affected Model(s): 8431-2X

Affected Product(s): EMS WATTMETER, 1-PHASE

Brief Description of the Problem:

Wiring error on the line #1 and #2 terminal jacks. Line #1 and #2 terminal jacks are reversed.

How to Fix:

Follow the procedure given in the "PF1060.pdf"

File(s) to Download (name / size):

PF1060.pdf (29 kB)

Full Description of the Problem: