Release Date: 2002/02/14

**Affected Model(s):** 6385, 6485, 8970, 9480, 9481 (-PX to -WX)

Affected Product(s): LVSIM-HYD 1.11, LVSIM-PNEU 1.01, LVSIM-EMS 2.1 r2, LVSIM-ACOM 1.2,

LVSIM-DCOM 1.0

## **Brief Description of the Problem:**

Drivers for the PCI network security device are missing on the CD-ROM.

## **Full Description of the Problem:**

The new network security device card uses a PCI expansion slot. The drivers required for this new card are not included on the CD-ROM.

## **How to Fix:**

Download and run the self-extracting file PF1039.EXE. Refer to the user manual of the affected models to install the PCI drivers for the network security device.

Note: In the procedure given in the user manual, replace the path X:\\Hardlockpci by the folder where you saved the files extracted from file PF1039.EXE. (usually C:\\LABVOLT\\PF1039)