



Thyristor Speed Controller(50-9017)

Product Fix: Student manual and instructor guide do not include laboratory experiments for the 9017 module.

Release Date: 2001/06/20

Affected Model(s): 9017

Affected Product(s): Thyristor Speed Controller

Brief Description of the Problem: Student manual and instructor guide do not include laboratory experiments for the 9017 module.

Files:

11627-00 - Investigations in Electric Power Technology
Student Manual - 11627_00add.pdf (339 kB)

11627-01 - Investigations in Electric Power Technology
Instructor's Edition (Wildi/De Vito) - 11627_01add.pdf (259 kB)

24769-00 - Electrical Power Technology
Investigations in Electric Power Technology - 24769_00add.pdf (339 kB)

24769-01 - Investigations in Electric Power Technology
Instructor's Edition - 24769_01add.pdf (258 kB)

25986-1A - Electrical Power Technology
Instructor Information and Answer Guide - Volume 1 - 4
25986_1AAdd.pdf (261 kB)

25987-0A - Electrical Power Technology - Volume 2
DC Machines - 240/415 V - 50 Hz - 25987_0AAdd.pdf (339 kB)

25990-01 - Electrical Power Technology
Instructor Information and Answer Guide - Volume 1-4 (Wildi/De Vito)
25990_01add.pdf (261 kB)