

Lab-Volt® Computer-Assisted 0.2-kW Electromechanical Training System(59-8006)
Product Fix: 9062-1x is not compatible with USB 3.0

Affected Model: 9062-1x

Brief Description of the Problem: The Data Acquisition Interface, Model 9062-1x is not compatible with USB 3.0 port.

How to Fix: You should use USB 1 or USB 2 port with the Data Acquisition Interface, Model 9062-1x.

Note: USB 3.0 connectors has a blue insert, this is not the case for USB 1 and USB 2 connectors.