Equipment Set TP 47224: Statistical Process Control (Stand-Alone) 8145063 (47224-00)



LabVolt Series

Datasheet



* The product images shown in this document are for illustration purposes; actual products may vary. Please refer to the Specifications section of each product/item for all details. Festo Didactic reserves the right to change product images and specifications at any time without notice.

Festo Didactic en 12/2024

Table of Contents

General Description	3	;
Manual	7	,

General Description

Build solid students' skill set in quality control

Quality is a fundamental component of the organizational strategy of most manufacturing companies to remain competitive. Modern industries have turned toward statistical process control (SPC) to control and improve quality.

The Statistical Process Control training package focuses on the practical applications of SPC. With the right combination of hardware, course content and software, future quality control technicians and engineers learn to collect, analyze, and interpret data using SPC tools commonly used in the industry.

Develop know-how applicable to the job market

Through hands-on activities, the Statistical Process Control training package enables instructors to efficiently convey the required knowledge and skills related to SPC. Comprehensive courseware offers a large range of exercises and projects arranged in a sequence of increasing complexity. This approach allows students to reinforce and expand their skills in a fluid way and improves transferability to the workplace. Guided exercises build basic know-how and confidence; realistic projects develop decision-making skills.

Build expertise with the right equipment

This training package includes measuring instruments and part samples carefully designed to highlight the most important aspects of data collection in the context of SPC. These parts are manufactured to ensure repeatability from one equipment set to another, giving teachers peace of mind when working with multiple sets. Also included are a software and data transmission cable learner will use to recreate a typical industrial data collection and analysis process.

Note

TP 47224, Statistical Process Control (Stand-alone) version does not require any other equipment whereas TP 47224-A, Statistical Process Control (Add-on) requires either TP 47220, Basic Dimensional Metrology (Standard) or TP 47221, Basic Dimensional Metrology (Value). Included measuring instruments and accessories

All the measuring instruments needed to perform the experiments:

- One digital caliper (only included with the Stand-alone version)
- One go/no-go plug gauge
- One go/no-go thread gauge
- One go/no-go pipe thread plug gauge
- One USB cable that automatically transfers measuring data to a SPC software

A complete coverage of dimensional metrology

In order for learners to provide reliable data to apply SPC, they need to correctly handle and read common measuring instruments. Consider Festo's TP 47220/47221, Basic Dimensional Metrology to enable beginners in the field to have a solid understanding of the fundamentals of dimensional metrology.

Learn more about this complementary learning solution here.

Learning outcomes

- Explain the relationship between quality and variability.
- Explain what a quality characteristic is and give real-life examples.
- Explain the difference between variables data and attributes data.
- Name the seven major tools of Statistical process control (SPC).
- Realize the importance of collecting and summarizing data in the industry.

- Recognize a frequency distribution.
- Identify the class frequencies in a frequency table.
- Identify the absolute and relative frequencies in a frequency table.
- Distribute raw data into class frequencies.
- Identify the main features of a histogram.
- Recognize common measures of central tendency and dispersion used in statistical process control.
- Describe the SPC feature available on some digital calipers.
- Collect variables data from measurements on a given component using a digital caliper equipped with an SPC output.
- Construct frequency distributions based on variables data obtained experimentally.
- Use a spreadsheet software to calculate the range of a data set.
- Construct histograms using a spreadsheet.
- Realize the importance of control charts in industry.
- Recognize a normal distribution curve.
- Identify the variance and mean of a normal distribution curve.
- Explain the properties of the normal distribution.
- Explain what a fluctuating pattern is.
- Explain the difference between natural variation and unnatural variation.
- Explain the difference between special causes and natural causes of variation.
- List the main characteristics of a natural pattern of variation.
- Recognize an x and R control charts.
- Identify the control limits and the center line in x and R control charts.
- Explain what three-sigma control limits are.
- Recognize the structure of the data used to construct x and R control charts.
- Describe the general procedure to construct x and R control charts.
- Describe some visual tests used to analyze x control charts.
- Give examples of special causes for unnatural patterns in x control charts.
- Identify the control limits and the center line of a quality characteristic analyzed with x and R control charts.
- Select the coefficients needed to compute the control limits of x and R control charts according to a sample size.
- Perform visual tests in x and R control charts to detect unnatural patterns of variation.
- Explain what process capability is.
- List the forms to express process capability in industry.
- Explain what a process capability index is.
- List some process capability indices used in industry.
- Interpret the process capability indices Cp, Cpk, Cpl and Cpu
- List the conditions that must be met to interpret process capability indices.
- Relate the process capability indices to the number of defective parts per million (ppm).
- Explain what an attribute is.
- List different types of control charts for attributes.
- List fixed gages used to evaluate attributes on workpieces.
- Identify go/no-go plug gages used in the industry and explain how they are used.
- Explain what the fraction nonconforming control charts are used for.
- Recognize the structure of the data used to construct fraction nonconforming control charts.
- Describe the general procedure to construct fraction nonconforming control charts.
- Recognize a fraction nonconforming control chart.
- Identify the center line and the control limits in a fraction nonconforming control chart.

- Inspect attributes of a workpiece using go/no-go plug gages.
- Identify the control limits and center line of a fraction nonconforming control chart.
- Use fraction nonconforming control charts to determine whether a process is in statistical control.
- Explain what acceptance sampling is.
- Explain what a sampling plan is.
- List different types of sampling plans.
- Name the components of a single-sampling plan for attributes.
- Define producer's risk and consumer's risk.
- Name the four considerations to set a single-sampling plan.
- Identify the elements of a Cameron table.
- Recognize a thread go/no-go plug gage used to check internal threads.
- Explain the use of thread go/no-go plug gages to check internal threads.
- Recognize an L1 plug gage for NPT threads.
- Explain the use of an L1 plug gage for NPT threads.
- Inspect threaded holes using thread go/no-go plug gages.
- Set a single-sampling plan for attributes. Also order student manuals and instructor guides which includes:
- Guided exercises to build know-how
- Projects to develop decision making skills
- Activities to reinforce transversal skills

Equipment Set TP 47224/47224-A: Statistical Process Control, The equipment to teach SPC tools in the context of dimensional measurements shall include precision measuring instruments and manufactured parts. Guided exercises and unguided projects shall be available for students to get an in depth understanding and hands-on practice on the use and interpretation of the main statistical tools of SPC. They shall use measuring instruments to collect data that will be analyzed using SPC tools on a computer. All instruments and parts shall be stored in a protective foam on a stackable tray equipped with handles.

This equipment shall not include a SPC-enabled digital caliper.

It shall include the following features :

- Outstanding repeatability from one set of parts to another
- Content available as e-Learning, PDF and printed format
- Exercises are followed by projects to develop decision-making skills
- Portable and stackable storage tray with handles
- Outline of each instrument and part is cut from foam block The following components shall be included :
- 1x USB cable that automatically transfers measuring data to a SPC software
- 1x go/no-go plug gauge
- 1x go/no-go thread gauge
- 1x go/no-go pipe thread plug gauge
- 3x parts that represent a common industrial part
- 1x sample of at least eleven parts that represent another common industrial part

The following learning aims for students should be covered with specific didactical documentation (available in physical or digital format):

- Explain the relationship between quality and variability.
- Explain what a quality characteristic is and give real-life examples.
- Explain the difference between variables data and attributes data.
- Name the seven major tools of Statistical process control (SPC).
- Realize the importance of collecting and summarizing data in the industry.
- Recognize a frequency distribution.
- Identify the class frequencies in a frequency table.
- Identify the absolute and relative frequencies in a frequency table.
- Distribute raw data into class frequencies.
- Identify the main features of a histogram.
- Recognize common measures of central tendency and dispersion used in statistical process control.
- Describe the SPC feature available on some digital calipers.
- Collect variables data from measurements on a given component using a digital caliper equipped with an SPC output.
- Construct frequency distributions based on variables data obtained experimentally.
- Use a spreadsheet software to calculate the range of a data set.
- Construct histograms using a spreadsheet.
- Realize the importance of control charts in industry.
- Recognize a normal distribution curve.
- Identify the variance and mean of a normal distribution curve.
- Explain the properties of the normal distribution.
- Explain what a fluctuating pattern is.
- Explain the difference between natural variation and unnatural variation.
- Explain the difference between special causes and natural causes of variation.

 ${\rm ${\odot}$}$ Fest ${\rm ${\circ}$}$ Didattiet the main characteristics of a natural pattern of variation.

- Recognize an x and R control charts.
- Identify the control limits and the center line in x and R control charts.

Manual

Description	Manual number
Statistical Process Control (Workbook (Instructor))	8122094 (81220-94)

Reflecting the commitment of Festo Didactic to high quality standards in product, design, development, production, installation, and service, our manufacturing and distribution facility has received the ISO 9001 certification.

Festo Didactic reserves the right to make product improvements at any time and without notice and is not responsible for typographical errors. Festo Didactic recognizes all product names used herein as trademarks or registered trademarks of their respective holders. © Festo Didactic Inc. 2024. All rights reserved.

Festo Didactic SE

Rechbergstrasse 3 73770 Denkendorf Germany

P. +49(0)711/3467-0 F. +49(0)711/347-54-88500

Festo Didactic Inc.

607 Industrial Way West Eatontown, NJ 07724 United States

P. +1-732-938-2000 F. +1-732-774-8573

Festo Didactic Ltée/Ltd

675 rue du Carbone Québec QC G2N 2K7 Canada

P. +1-418-849-1000 F. +1-418-849-1666

www.labvolt.com

www.festo-didactic.com