



Unit 4: Ex. 2 The Zener Diode, Procedure 6 of 14: Changed tolerances

**Directions:**

TechLab 6.0 & higher:

Download the file F50050040E.zip to your desktop. Then, extract F50050040E.tbk to the Tlssystem\unit\F50050040E directory on your TechLab server, overwriting the existing file.

Course Title: Revised version number

**Directions:**

TechLab 6.0 & higher:

Download the file F500500E.zip to your desktop. Then extract the entire contents to the tldata\gp2 directory on your TechLab server, overwriting the existing files.